

CSVA 2011 Conference Toronto, Ontario
Nov 14 -16, 2011

**Assessing Value in Roundabouts vs. Signals - Highway
17/94/Centennial Crescent East Intersection**

**Manal Kasim, P. Eng.
Area Engineer
Planning & Design Section
Ministry of Transportation
North-eastern Region**

Topics

- **Project Stages**
- **VE Study Set-up**
- **Information Phase**
- **What is the problem?**
- **Field Review Benefits**
- **VE Workshop**
- **Speed Management Measures for Roundabout**
- **Safety Risk Analysis Contribution**
- **Independent Study Findings**
- **Roundabout Configuration**
- **Roundabouts with high-speed approaches - Other locations**
- **Conclusion**

Project Stages

Detail Design – February 2011

- Resurfacing / Rehabilitation – approximately 12.8 km
- Improvements to Hwy 17/Hwy 94 – included in the project
 - No preliminary design

VE Study - March 2011

- Viable options for a Long term intersection solution

Independent Study by a Roundabout Specialist - June 2011

- Suitability of Roundabout
- Mitigation for high speed approaches

Location Map



Roundabout under construction in Mattawa ~ 55 km east of the Highway 17/94/Centennial Crescent East Intersection

VE Study Set-up

- Five-day VE Workshop
- Independent team (16 members – including 6 MTO staff)
 - Highway safety Specialist /Roundabout Specialist
 - Traffic Engineer/Roundabout Specialist
 - Human Factor Specialist
 - Cost Estimator/Highway Engineer
 - AutoCAD/Highway Engineer
- All alternatives were developed using AutoCAD
- VE Estimator prepared costs for all alternatives to ensure consistency
- Followed standard MTO study plan with Fast Diagram, Project Risk Register as well as Performance Criteria & Measures

Information Phase

Highway classification

Hwy 17 - King's Highway; RAU 110 km/h

Hwy 94 - King's Highway

Centennial Crescent - Municipal Road

Posted speed: Hwy 17 - 90 km/h, Operating speed – 99 km/h - 85 percentile – Speed Study 2010

Posted speed: Hwy 94 - 80 km/h

Centennial Crescent East- 60 km/h, West leg about 6 km apart

Growth forecast: 1.5%

AADT: 7,600

% of Commercial Traffic -11.6 / 2006 data

Information Phase, Cont'd

Hwy 17 – Wide Cross Section

- Left turn lanes - EB and WB
- Through lanes
- Right turn lane – EB, Right Turn Taper – WB
- Vehicle accessing Hwy 17 from parking lot restricts visibility for Vehicle accessing Hwy 17 from Hwy 94




Hwy 94

- Shared left /through lane
- Channelized right turn
- Stop Control

Centennial Crescent East


- Shared left / through /right lane
- Stop control



Information Phase, Cont'd

Existing Electrical

- Overhead flashing amber beacon installed
- Partial illumination - MTO owned: 3 poles
- Conduit installed in 2000 for future traffic signals



Information Phase, Cont'd

Vertical Alignment

- Flat grade at the intersection
- EB visibility of intersection limited by vertical alignment west of the intersection-hill

Horizontal Alignment

- Hwy 17 - tangent
- Hwy 94 and Centennial Crescent East - curves approaching the intersection

Existing Entrances

- Gas Station/Convenient Store - south east quadrant
- Chip Stand in the parking lot ~ 50 m from intersection- south west quadrant
- Residence\ businesses in the vicinity east north quadrant

What is the problem?

- Municipality concerns- excessive speed at the intersections
- MTO speed studies for the intersection 1978/1999/ 2010 - speed is appropriate
- Turning collisions predominant, severe collisions/injuries – point to operational problems
- Heavy left-turn movement from Hwy 94 to Hwy 17 W (Commuter Traffic) – unsatisfactory level of operation LOS F
- AADT increase - reduced gaps for minor roads entering major road during peak hours & conflicting movements.
- Traffic signals warranted due to volumes and delays at intersection - met combination criteria – Not installed due to concerns
- Outside peak hours adequate gaps available for minor street traffic

Field Review Benefits

- Existing illumination pole creates blind spot for Hwy 94 vehicles
- Vehicles on Hwy 94 advance beyond the stop bar at an angle to have better visibility
- Route Marker Sign and TOD signs limit sightlines



Centennial Crescent looking east on Hwy 17



Hwy 94 looking east on Hwy 17

VE Workshop

Performance Criteria

Constructability/Staging, environmental, safety and traffic Operations

VE Proposals

- **51 ideas - 13 VE proposals - 3 Scenarios developed**

Scenarios

- **Signalization** with speed management – highest value solution – lowest cost
 - Double Long Distance Detection on EB and WB with speed management
 - Install advance warning sign and beacon on the WB approach/east of intersection
 - Change in collision frequency & severity associated with the introduction of signal control is minor
 - Slightly reduce right angle collision - Potential for run through red - non compliance - creates additional operational concerns.
 - Reduce delays for minor roads – increase delays for Hwy 17
 - 40% of Hwy 17 traffic will stop during peak hours –drop off during the day and significantly overnight
 - Speed management challenges
 - Low driver expectation of a new signalization - No signalized intersection ~ 155 km east of intersection - Deep River, 1.5 - 2-hr drive and ~ 10 km west of the intersection

VE Workshop, Cont'd

- **Roundabout** with speed management – highest safety and operating performance for at grade option – higher cost
 - Safer - Decreases all collisions relative to signalized intersection
 - Collision severity reduced
 - Low peak-hour delays – average < 10 seconds – LOS A for all approaches
 - Continue to operate with high LOS well beyond the 2035 horizon year
 - 100% of Hwy 17 traffic slow down all day & about 5 -10% stop during peak hours
 - Public / trucking industry acceptance
 - Night time noise impacts
- **Diamond Interchange** – highest cost

Speed Management Measures for Roundabout

- Long splitter islands – informs drivers of the intersection ahead and creates "friction" to reduce operating speeds
- Transition to semi-urban cross section. Outside (semi-mountable) curbs in advance of the entry to the roundabout and beyond the roundabout exit
- centre island design to block sightlines through the roundabout. Grading and landscape planting to increases visibility/awareness of the roundabout and block headlight glare from opposing vehicles on the offset approaches.
- Coloured textured surface truck apron can be used
- Full illumination to beyond the splitter islands on all approaches.
- curvilinear approach alignments. Back to back curves to emphasize the intersection

Speed Management Measures for Roundabout, Cont'd

- High visibility signage and markings:
 - “Roundabout ahead” signs with advisory or regulatory speed tabs well in advance of the intersection to allow for stepped speed reduction.
 - Flashing beacon and/or using an oversize sign to increase awareness
 - “Yield ahead” signs well in advance of the intersection.
 - Enhanced pavement markings approaching the intersection - wider edge lines
 - Keep right sign and object marker at end of splitter island.
 - Advance diagrammatic roundabout directional signs on approaches

Safety Risk Analysis Contribution

Stop Controlled (Existing) Vs Signalized Intersection

- Change in collision frequency & severity associated with the introduction of signal control is minor
- Annual collision cost is about the same for stop controlled and signalized intersection with speed management
- Annual collision cost for a roundabout is substantially less

Signalized Intersection vs. Roundabout

- 76% reduction in injury when changing from signalized intersection to roundabout - *FHWA

* Federal Highway Administration (**FHWA**) is an agency within the U.S. Department of Transportation - *supports State and local governments in the design, construction*

Independent Study Findings

Confirmed VE findings – Roundabout performs better in terms of safety and operations

Signalization

- Projected fatal + injury collision frequency – 0.7 collision per year if Intersection converted from stop condition to signalization
- Potential increase in rear-end collisions - 58% as per Highway Safety Manual
- Speed control treatments are required

Roundabout

- projected fatal + injury collision frequency - 0.29 collisions per year based
- Shorter delays and queues
- collision severity reduced
- Effective in reducing head-on and T-Bone collisions
- Speed control treatments more naturally lend themselves to implementation with roundabout

Roundabout Configuration

- Single lane
- Diameter 43 m
- Speed at roundabout - 42km/h
- Truck apron
- Design Vehicle WB-20



Roundabouts with high-speed approaches - Other locations

- *Hwy 26 at Wasaga Beach*
 - *Four-lane divided rural*
 - *90 km/h posted speed*
- *Hwy 7 at St. Mary's*
 - *two-lane undivided rural*
 - *80 km/h posted speed (100 km/h operating speed)*
- *Hwy 406/East Main Street in Welland*
 - *at end of a four-lane freeway*
 - *100 km/h leading posted speed*

Conclusion

- VE was used as an alternative to preliminary design to develop viable options for the intersection improvements
- VE accelerated the schedule by eliminating the preliminary design stage
- VE Team composition is important: Team included Roundabout specialist, Highway safety specialist, Traffic Engineer and Human Factor Specialist to address the intersection issue
- Road Safety Risk Analysis and Traffic Evaluation reports of the alternatives including existing condition are important
- Economic analysis should not be the only means of evaluation intersection control alternatives
- Introduction of new intersection control in high-speed context-not expected by drivers-will likely increase rear-end collisions
- Speed control treatments are required to enhance driver awareness
- Project Risk Register and mitigation measures developed during the workshop were helpful
- VE provides the owner with the opportunity to make an informed decision based on either cost or performance without compromising the function.



Thank You

Contact Information:

**Manal Kasim, P. Eng.
Area Engineer
Planning & Design Section
Ministry of Transportation
North-eastern Region
Email: [***manal.kasim@ontario.ca***](mailto:manal.kasim@ontario.ca)**